

**RECEIVED
CENTRAL FAX CENTER**

Customer No.: 31561
Application No.: 10/064,454
Docket No.: 8327-US-PA

SEP 15 2004

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In Re Application of:

KUO et al.

Examiner : John M Ross

Serial No. : 10/064,454

Art Unit : 2188

Filed : 07/17/2002

Docket No. : 8327-US-PA

For : Control Chip and Method For
Accelerating Memory Access

No fee is believed to be due. However, the Commissioner is authorized to charge any fees required in connection with the filing of this paper to account No. 50-2620 (Order No.: 8327-US-PA)

**AMENDMENTS AND REQUEST FOR CONTINUED EXAMINATION (RCE)
UNDER 37 CFR § 1.114**

U.S. Patent and Trademark Office
Commissioner for Patents
220 20th Street South
Customer Window, Mail Stop **RCE**
Crystal Plaza Two, Lobby, Room 1B03
Arlington, Virginia 22202

Dear Sir:

The Advisory Action mailed Aug. 9, 2004 has been carefully considered. Pursuant to 37 CFR § 1.114, Applicants respectfully request continued examination of the above-identified application in consideration of the following Amendments and Remarks.

Page 1

BEST AVAILABLE COPY

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.